

Received from Chief Ship Surveyor

4 JUN 1956

REPORT

Sng.

No. 11317

"IA PAZ"

SHIP'S NAME

standing Conditions of Class: Subject to keel plates Nos. 4, 5 & 8 from forward and keel plates in way of E.R. D.B. tank (wasted) being examined and dealt with as necessary, also to sounding pipes in cargo spaces being adequately protected, by the Special Survey.

orsement of Class (B) (~~ASXBXBXBX~~ None)

veys due: SPECIAL SURVEY (C) due 10.55. Postponement until 9.56 approved 20.1.56 provided a satisfactory General Examination (Circular No. 1959) is held in dry dock. See also later correspondence.

are of Present Survey: (Afloat ~~and in dry dock~~)

Commencement of General Examination as above: Temporary repairs to bottom shell riveting in way of aft bilge well in E.R.

cial Features: Owners' Representative has stated that the General Examination will be completed on ship's return to Singapore in approximately 1½ months' time.

Interim Certificate in order (Yes-No-None)

ns Outstanding: (~~XXXXXX~~ for S.S. ~~XXXXXX~~)

ALL ITEMS.

PORTION OF G.E. HELD:- See this report.

to be completed by:

ommendation:

SUBMITTED ACTION be DEFERRED for Special Survey, subject as above, to permanent repairs to defective shell riveting in way of E.R. well and to D.B. tank top plating in E.R. (Pitting) being examined and dealt with as necessary next Special Survey.

As Now. Subject.

G.E. PART HELD.



©

31-5-56

Lloyd's Register
Foundation