






  
 11 11
   
 3/4 x 1/2 long x 1/2 deep

Some minor help keel repairs carried out

Nothing has been done at this time to the E. Room tank top of latrine which was examined & remains excellent as is also the S. latrine building on ship post.

Nothing has been done at this  
to the incised shell plate which remains exposed.

Ch.

## ANCHORS.

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

Iron Stream Chain }  
or Steel Wire.... }

General Committee  
Thursday, 17th December, 1933.