

For the information of Surveyors and the Committee only.

Received at

Office

27 AUG 1920

# Lloyd's Register of Shipping.

(Report on Vessel No. 41179. Port Hull)

No.            SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Mason & Jopling & Sons Ltd. of Sunderland for the Vessel No. 678, being built by Earls Shipbuilding & Eng. Co. of Hull have been inspected by me as set forth below and found to be, so far as can be seen, Sound

on ~~Forgings or Castings~~.

P. Dronbace & J. Dale  
2 Propeller Brochets - Sunderland

Lloyd's  
No. 5891  
J.D.  
13.6.30

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...		Cast-Steel	
made ...		Electric Furnace	
annealed ...		Yes	
Dimensions ...		As per plan	
Pressure on Inspection ...		bleaching & testing	
When Inspected ...		13.6.30	
		28.6.30	
CASTINGS.			
Tests on Standard Test Pieces.			
Wedge Test—		30°	30°
Extensions per square inch ...		25%	21%
Extension per cent. ...		120°	120°
Bending Test—			
Angle before fracture ...			
Hammer Test—		Hammered only	
Weight from ground ...			
Tempering Test—			
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £

To be paid at

If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

29. T.

008158-008167-0193



© 2021

Lloyd's Register Foundation

Dated