

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

"TAIZIN MARU"

Smk.

2583.

VESSEL'S NAME.....Rpt.....No.....

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The SHIMONOSEKI Surveyor reports this vessel placed in dry dock, bottom coated and on account of damage through stranding, a considerable number of shell plates, frames, floors, tank top and stringer plates etc., repaired or renewed.

A fresh record of survey is not desired.

It is submitted the vessel appears worthy to remain as classed without fresh record.



14.8.40



© 2020

Lloyd's Register
Foundation

008168-0876-0003