

DISCLOSED SECTION

Rpt. 8.

No.

(Received at London Office)

Lon. No. 117517A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of ...

No. in Survey held at ... Date, First Survey ... Last Survey ... 19... (No. of Visits ...)

78385 on the Mod. Iron or Steel MV TANKHAVEN III

TONNAGE :-
GROSS 3262
UNDER DK. -
NET 1688

Built at Panama City, Fla By whom J. A. Jones Const Co Inc. When 1945

Owners N.V. Gebr. Van Hater's Scheep en agentuur cheats. Owners' Address ... (If not already recorded in Appendix to Register Book)

Managers ... Port belonging to Rotterdam

Surveyed Afloat or in Dry Dock? ... Name of Dock ... Destined Voyage ...

all DBor DBa ... feet; uE & B ... feet; f ... feet
al capacity ... tons. FPT ... tons; APT ... tons; MT ... feet tons.

Only alterations in the existing records of tanks should be inserted.
N.B. All alterations in the existing records should be underlined.

last Report, No BC Summary Port No. 2459

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	Machinery and Boiler
* for Special Survey.	Survey
Date of last Survey and of Periodical Surveys.	(Including date of N.B., if any).
BS. Tanker 249.	MBS 11.45
Annual Survey	MS 3.48
2, 49.	D.B.S. 3.48
	T.S.C.L. 2.49
Carrying petroleum in bulk oil tank.	
Oil - F.P. below 150°F	
also welded.	
Society's Freeboard (if assigned) as ... ft ... ins.	
painted on Ship and now verified	

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Condition of Decks	Celling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Platings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Fastenings	Rudder	Scuppers	Boats
Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" In way of sidelights	Windlass	Hatches	Condition, how ascertained
	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Ordinals	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Decks	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Tanks been examined internally?	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Tanks been tested?		" " at other places	" Rule length size
		Stringers, Clamps & Shelves	Chain Locker
		Salting	Hawsers & Warps
		State if examined.	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38."

Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (If any)	£	:	:	19
Travelling Expenses (If chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (If any)	£	:	:	19

Committee's Minute. FRI. 1 SEP 1950
Charger Assigned. Withdraw BC class

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday 14 September 1950
Lloyd's Register
Classification Committee's decision
Foundation

008186-008200-0101

As certificate required? If so, to be sent to