

1

14 APR 1925

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

J.W. P. Leasowe.

Report

No. 88800 a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw shaft

When due

12.24.

The screw shaft of this vessel became due for survey at the end of December last.

In reply to enquiry, the Owners Engineer has informed the Society's Liverpool office that it is not intended to continue the classification of the vessel.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...

Ans. B.A.
9/4/25



Lloyd's Register
Foundation

008186-008200-0143