

372

1

Received from Chief Surveyors.....

REPORT No.

For the **CHIEF SHIP SURVEYOR** and **CHIEF ENGINEER SURVEYOR.**

In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92)

Survey.....

When due.....

A letter has been received from the Principal Surveyor for America enclosing one from the Owners, intimating their decision to withdraw the class of this vessel.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book and 3 dots (...) be inserted in lieu, indicating withdrawal of class at the Owners' request.

```
Withdraw class
Insert (...)
```

14.2.45

© 2020

Lloyd's Register

008201-00820-001

By H. G. HOUSE.

Standing and Running Sails