

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3
9th July, 1951.

Dear Sir,

Steamer "JOHN P.G."

With reference to Baltimore Report No.10222, it is concluded that the safety valves of the LP steam generator were adjusted to 125 lb./sq. in., and that all pumps intended for essential services at sea have been made under survey.

I shall, however, be glad if you will kindly let me have the Surveyor's confirmation on this point.

At the same time, will you please obtain from the Surveyor and forward to this Office the propeller certificate, as this does not appear to have been received.

Yours faithfully,

Assistant Clerk to the
Classification Committee.

The Secretary,
NEW YORK.



© 2020

Lloyd's Register
Foundation

008201-008210-2153