

m.v. "HENRY DUNDAS"

Hamburg Rpt.22296.

IT IS SUBMITTED the Hamburg Surveyors  
be informed their letter of the 5th instant has been noted.

In this connection it should be pointed out  
that the high voltage test of the generator has been made at  
1500 volts, whereas the test should have been carried out at  
2000 volts in accordance with Appendix 2, Clause 6 of the Rules.

The Surveyors comments are awaited.

*J. G. J.*

27. 5. 1937.

*Law*



© 2021

Lloyd's Register  
Foundation

008217-008221-0129

To Mr Cook

PAID

10/10



© 2021

Lloyd's Register  
Foundation

