

21 SEP 1953 4E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME

"SASEBO"

REPORT

Cff.

No. 58456.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO~~ DAMAGE THROUGH wire fouling  
propeller.

Docking. Propeller and fastenings satisfactorily examined.

IT IS SUBMITTED that this vessel is eligible to remain as classed.



© 2020  
18.9.53.

Lloyd's Register  
Foundation

008231-008236-0192