

# Lloyd's Register of Shipping

SALVAGE ASSOCIATION BUILDINGS, CLARENCE ROAD

Empire House, Mount Street, Cardiff,



Cardiff, 22nd. February 1950

Dear Sir,

Steam Trawler "SASEBO"


With reference to your letter of the 20th. instant, regarding this ship, drillings in A strake (Garboard) were not taken at forward and after ends because of cement being fitted over these strakes at ends. The cement was hammer tested and found adhering satisfactorily.

The midships drillings in A strake (Garboard) were obtained when the deep cement had to be removed to facilitate repairs to the bottom structure.

We are, Dear Sir,  
Yours faithfully,  
The Surveyors,  
per:-

The Secretary,

LONDON.



© 2020

*David Thomas*

Lloyd's Register  
Foundation

α 8231-α 8236-0195

13

Referred to Mr. Perris.

RS

U.S. Pat. 6.1 55. 1868.

RS  $\frac{24}{2}$  50.



© 2020

Lloyd's Register  
Foundation