

DAMAGE Cause not stated

7 - NOV 1945

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME "FRESHBROOK" REPORT Gls. No. 70078

For the CHIEF SHIP SURVEYOR ~~and~~ CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

% of Survey Damage. When due

Subject to indented Ficle side plating etc (s.s.) being dealt with at the first convenient opportunity.



© 2021

Lloyd's Register Foundation

Wals 31.10.45

008237.008247.0050

names good in space around

Have pumps been examined and found effi-

Planking

Common, ho (State if w Equipment b