

Ceiling in Holds, thickness and material *None*

Cargo Battens, thickness, material

Req. 1.

(Received at London Office, *22 SEP 1941*)

No. *1342* Port *Lpool* Date *12th Sept* 19*41*

we request that the *Three water tank vessels* Building
for *Admiralty* by **THE LYTHAM SHIPBUILDING and
ENGINEERING COMPANY, LIMITED**

of *264 Gross* Tons. Length, *120'-0"* breadth, *24'-6"* depth, *12'-6"*

may be Specially Surveyed while building (*100 A.1.*) If for a particular term
or class, state the same.

we hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, and,
in addition, any travelling and other expenses which may be incurred by the Surveyors in connexion
with the survey.

In no case can the vessel be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping,
which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register
Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member
thereof, or the Surveyors, or other Officers or Agents of the Society."

No. *868* ✓ in Builder's Yard. Manufacturers of Engines **THE LYTHAM SHIPBUILDING and
ENGINEERING COMPANY, LIMITED**
869 ✓ Ditto of Boilers
870 ✓ *Sw. Auth.*
871 ✓ *23/9/41*
872 Signature *R. Friedmanthal*

To the Secretary,
873 Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.



008237 008247 0058

✓

2

2001

LL

TUR
ED P
NOT

- 868 - Freshbrook.
- 869 - Freshenet
- 870 - Freshlake
- 871 - Freshmore
- 872 -
- 873 -



© 2021

Lloyd's Register
Foundation