

In damage cases where the Surveyor has not made a special damage report he is required to state whether he

Society's Ex-

008237-008247-0302

TELEGRAMS: COMMITTEE, FEN, LONDON

AR
COPY

TELEPHONE: ROYAL 3551 (6 LINES).



Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

7th February, 1949.

Dear Sir(s),

Stm. Tlr. "LADY STANLEY".

With reference to the classification

of the above-named vessel in the Society's Register Book, I am directed to remind you that the Special Survey of the Boilers prescribed in the Society's Rules is now due, and I shall be obliged if you will kindly state for the information of the Committee what arrangements will best suit your convenience to have the necessary inspection held.

Yours faithfully,

Messrs. Stephen Fishing Co., Ltd.,
172, Market Street,
ABERDEEN.



R. J. Sladden

Clerk to the
Classification Committee.

11,48

Stringers

Have Ventilators and their Coamings been

Timbers of Frame at openings