

7 - NOV 1945

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME "LADY STANLEY" REPORT Hul. No. 53140

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to indented shell plates B.8 & 9 and C.10 (s.s.) at the Owners' convenience.

The HULL Surveyors report this trawler placed on slipway and bottom coated.

IT IS SUBMITTED the vessel is eligible to remain as classed with record of survey 10.45 subject as above.

10.45 Hul. subject.



29.10.45

© 2021

Lloyd's Register  
Foundation

008237-008247-0305

Keelsons .....

Stringers .....

efficient? .....

Have Ventilators and their Coamings been

Timbers of Frame at openings

at other places

Chain Lock