

Ind. 2841-25 SEP 1947

Rpt. C. 11 (Contd.)

Index No. ....

# Lloyd's Register of Shipping.

Ship's Name "RICHMOND HILL"

Official No. ....

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines  
in .....

The following alterations have now been carried out:-

In way of starboard 'tween deck bunker spaces - Gunners' temporary  
accommodation removed and 7 sidelights in way removed and blanked off with  
riveted spigot closing plates.

3 sanitary discharges removed and efficiently blanked off with spigot  
closing plates.

Companionway and steel closing plate on original bunker tonnage hatch removed and  
rest bars, cleats, battens, wood covers and tarpaulins restored to original  
condition.

One 8" dia. ventilator removed from weather deck and opening in deck plating  
closed by an efficient E.W. steel plate.

*AMB Edwards*  
SURVEYOR TO LLOYD'S REGISTER.

H U L L. 18.8.47.

Noted. *AS*  
© 2020 26 SEP 1947

Lloyd's Register  
Foundation

008279-008287-0072