

S.

Closures.

*Lloyd's Register of British
and Foreign Shipping.
56, John Street, Sunderland.*

LLOYDS REGISTER
LONDON.

REC^d 12 FEB 1903

ANS^d 12/2/03

11th. February, 1903.

The Secretary,

London.

Sir,

I have to acknowledge the receipt of your letter of the 10th instant, enclosing a letter from the Owners of the new steamer "Margarita" with Sunderland Reports No. 21224 on this vessel.


In reply I beg to state that the facts are as stated by the Owners, the vessel struck the dock wall in consequence of the breaking of a steel wire hawser when about to proceed to sea from South Dock, Sunderland on 18th January, 03., when fully laden.

Her rudder frame was renewed, and while I do not think any damage will be found to the stern frame or gudgeons I ^{thought} ~~think~~ it desirable to recommend that the vessel should be examined in Dry Dock on her return from the present voyage.

The Reports and Owners letter are herewith returned.

I am, Sir,

Your obedient Servant,



Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor,

C.D.

12 FEB. 1903

Also for Mr. Hill to note.

*C. D.
12/2/03*



© 2021

Lloyd's Register
Foundation