

Chief Surveyors.....

Received from Chief Surveyors.....

NAME "COPINSAY" REPORT PIRAEUS letter No 31.1.56.


For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey		When due	
	LMC MS.	12.51.	- not held.
	BS.	4.54.	- not held.
	Screw shaft Survey.	9.53.	- not held.

The Surveyors state that this vessel has now been classed with the Bureau Veritas.

IT IS SUBMITTED that so far as the machinery is concerned the class is this vessel might be deleted with a red line indicating non-compliance with Survey requirements.



© 2020 15.2.56.

Lloyd's Register
Foundation