

Latest date of internal examination of each boiler 26/5/39

Present condition of funnel(s)

008364-008374-0175

1138

11 JUL 1939 2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Notre Dame de Loretti

Rpt.

Boulogne

No.

747

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S. No.~~


This Survey, due 6.39 now partly held now

completed, and the following repairs carried out (due to wear & tear):-

It remained on account of wastage. Minor repairs effected to engines & pumps.

It is submitted the vessel is eligible to remain as classed, with notation of B. 6.39 S.N. 6.39 as recommended.

Note part ms



© 2021

Lloyd's Register Foundation

Thru 10.7.39

Thrust shaft removed and shoes, collars, thrust block, bearings examined & placed in