

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

30 JAN 1954

NAME "HELLENIC CHRYSSOULA" REPORT Cff. No. 58623

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ship is almost 44 years old and classed BS.

SPECIAL SURVEY TYPE 4 became due 6,52 but postponement until 6,53 approved 18.6.52 provided a satisfactory General Examination is held on ship's return to U.K. by 9,52.

ACTION is DEFERRED for Special Survey by 6,53.

In reply to various requests as to when the General Examination is to be held, the Owners have stated that the ship is laid up. The Notation "Laid Up-Surveys Overdue" inserted in the Register Book 15.7.53.

The CARDIFF Surveyors report (10,53), ship examined afloat and the requirements of SPECIAL SURVEY TYPE 4 due 6,52 now partly complied with.

Substantial repairs have been recommended for renewal of deck plating, framing, etc. but these repairs have not been carried out.

TO COMPLETE THE S.S.:- See this Report.

The Surveyors state that the ship remains laid up meantime.

In view of the year of grace having expired 6,53 the case is submitted for the consideration of the Committee.

ENDORSEMENT OF CLASS (B).

Stem and stem plating set over.
Indents in tank top plating.

S.P.K.
29-1-54



© 2021

Lloyd's Register

008386-008792-0036
Foundation