

It is submitted the attached

list of shell thicknesses
Built 1910.

E CHRYSSOULA Report No. _____

ESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in *100 THS.* of an inch.

	AMIDSHIP.				FORWARD.				AFT.				REMARKS.
	Original Thickness.	Thickness by drilling.	Diminution if any.		Original Thickness.	Thickness by drilling.	Diminution if any.		Original Thickness.	Thickness by drilling.	Diminution if any.		
	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	
AKC..	30				30								
J	50				30				40				
H	80				40				40				
G	64				40				40				
F	48				40				40				
E	48				40				40				
D	48				40				48				
C	48				40				48				
B	48				40				52				
A	52				46				54				
EL.	74				54				54				

This copy to be retained in office.

Drillings at ends to be made in the vicinity of the peak bulkheads.

008386-008392-0066