

in way of Double Bottoms at Solid Floors.
" " at intermedt. Bkts.
" " of Frames from centre to centre amidshine

" " in Hold " " pillars ✓

ches
Rule
Or a s
Inches
per Rule
Appro

2nd, 3, 10.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "SYRIER"

Report 61s. No. 39729

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

Nature of Survey _____

When due _____

100 A. 1. (steel)

1 DK. (steel)

Cell DB 211' 386t.

FPT 21t.

APT 15t.

FK. 4 BH. Cem.

Lloyds A & C.P.

P 27', B 57', F 27'.



© 2020
AEB.
19.3.20

Lloyd's Register
Foundation

008393-008400-0228

Height of Outside Brackets above at bilge

14	14	14	14
----	----	----	----

" Deck. * Iron or Steel, for _____ lng.

" Wood Deck. Material & thickness

" Deck Staining Plate height & thickness