

DISCLOSED
SECTION

Rpt. 8.

No.

(Received at London Office)

No. 115434 A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report

When handed in at Local Office

Port of

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

08580

on the ~~Wood-borne~~ Steel SS "ELIRO"

TONNAGE :-

GROSS 150

UNDER DK. 133

NET

Built at Portsmouth

By whom Philip & Son Ltd.

When 1909

MONTH 6.

Owners Soc. Rimerchietoni Rimiti

Owners' Address

(If not already recorded in Appendix to Register Book)

Managers

Port belonging to Station

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell DBor DBa

feet ; uE & B

feet ; f

feet

total capacity tons

FPT tons ;

APT tons ;

MT

feet

tons

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 115872 Port LON

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Survey should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER	Machinery and Boiler
for Special Survey	Surveys
Date of last Survey and of Periodical Surveys	(Including date of N.B., if any)
+100 A. 1. 47	+L.M.C.
towing pumps	MS. 6. 47.
11. 47.	MS. 10. 47
88 Ram 11. 47 (88)	TS 10. 47.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

S, OR EXAMINATION AS PER RULE, FOR

OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
ved ...								
ved and Fairred or Repaired								
or Repaired in place								

CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M.
stenings	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
ng	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
in way of sidelights	Rudder	Scuppers	Boats
nes	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
	Windlass	Hatches	Condition, how ascertained
	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Stringers	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Inner Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diamr.
Have the Tanks been examined internally?	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Have the Tanks been tested?		" " at other places	" Rule length size
		Stringers, Clamps & Shelves	Chain Locker
		Salting	Hawsers & Warps
		State if examined.	Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £ :

Special Damage or Repair Fee (if any) (per Sec. 29) £ :

Travelling Expenses (if chargeable) £ :

Second Surveyor's Fee (if any) £ :

Committee's Minute

Character Assigned

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of Shipping.

to Lloyd's register

Withdraw class

a msmt (...)

General Committee

Thursday, 4th November 1948

Classing Committee decision

Confirmed. P.B.

008428-008433-0126