

6th September, 1955.

ROTTERDAM.

9737, 845, 908, 36, 43, 50, 65 - As recommended.

M.C.39962 - As recommended.

9581 "LENA". As recommended. I do not appear to have received a reply to my letter of the 10th May regarding the moment of inertia of the 4200 mm diameter propeller and I shall be glad to receive this information by return of post.

9933 "DOMBURGH". As recommended. I have to point out, however, that the machinery has in the past been dealt with under the Continuous Survey arrangements and in the circumstances the reason for a Modified Survey being carried out at this time is not fully understood. I shall, therefore, be glad if you will kindly let me know whether the owners wish to revert to complete and Modified Surveys or whether they intend to continue with the Continuous Survey arrangements.

/Cont'd....

Lloyd's Register
Foundation