

are subject to non-occurrence of Labour Disputes, Lock-Outs, Fire, Accidents, and other unforeseen contingencies.

GRAPHIC ADDRESS,  
WEST HARTLEPOOL.  
HEAD OFFICE,  
SHIPYARD, WEST HARTLEPOOL.  
ED & TRANSFER OFFICE,  
LL, AUSTIN FRIARS, E.C.2.

TELEPHONE SERVICE:  
MIDDLETON SHIPYARD. HARBOUR DOCKYARD.  
TELEPHONE N<sup>o</sup>3 No. 2.  
204, 205 & 206.  
REPAIRS DEPT. N<sup>o</sup> 211.  
EMERGENCY " 398.


# Irvine's Ship Building & Dry Docks Co. Ltd

SHIP BUILDERS, ENGINEERS AND REPAIRERS  
MIDDLETON SHIPYARD AND THE HARBOUR DOCKYARD.

GRAVING DOCKS,  
380 AND 376 FEET LONG.

## West Hartlepool.

May 20th 1925.



essrs Lloyd's Surveyors,  
West Hartlepool.

ear Sirs,  
S.S. "Lima".


As requested by Mr. McAuslan we give you below  
particulars of the draught, freeboard etc for the above vessel  
s shown on our data sheets. We regret we have no copy of the  
original Germanischer Lloyd assignment of freeboard.

Mean load draught to disc	24'5"
Freeboard to top of statutory decline	5'0½"
statutory decline } equals 3½" above beams	
Winter freeboard	5'5½"

Yours truly,

FOR IRVINE'S SHIP BUILDING & DRY DOCKS CO., LIMITED.

*Bryant Roberts*  
Manager



© 2021 Lloyd's Register Foundation

008434.008438-0162