


COPY

LLOYD'S REGISTER OF SHIPPING



**This Certificate
Accompanies
REPORT**

Port

YOKOHAMA

No.

324

Dated

10-5-60

10th May, 1960

This is to Certify that ~~I~~ have

Surveyed the Machinery of the "MS. NAGASHIMA MARU" 3903 tons gross
at Tokyo whilst the vessel lay in dry dock and at Kawasaki on the
3rd May 1960 and subsequently for Docking, Tail shaft survey, Continuous
survey of engines and Aux. boiler survey

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
us in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
TS(CL) 5/60, ABS 5/60 and CS(with date) when the survey has been completed
and that her Machinery Classification Record be continued in the Book.

Parts now examined:
(C.S. Items only)

Sea connections

Main engine:- Nos.2 & 5 cylinder unit:- cyls., covers, pistons
valves and gears, connecting rods, top ends and
guides, crank pins and bearings.
No.4 main bearing and journal.
No.3 scavenge pump cyl. cover, piston, rod and lever.
Nos.2,3 & 5 intermediate shaft and bearings.

P.T.O.

D.N. Clayton

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS (CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS (OG) Tailshaft Survey—Oil Gland

ft

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 1,60 KOB

© 2020
Lloyd's Register
Foundation

008439-008445-0107