

Report of Survey for Repairs, &c., of Engines and Boilers.

SAT. NOV. 20 1920

(Received at London Office)

Port of Milford

Survey held at Pembroke Dock Date, First Survey 2nd Sept Last Survey 30 Oct 1920

on the Machinery of the Wood, Iron or Steel Trawler George Darby Master

Gross 276 Vessel built at Painley By whom Rowth & Co When 1918-10

Net 113 Engines made at Swanpool By whom Fawcett, Preston & Co When 1918

Boilers, when made (Main) 1918 (Donkey) 1918

Owners The Admiralty Port London Voyage Fishing

If Surveyed Afloat or in Dry Dock (State name of Dock) Pembroke Dockyard

CHARACTER.	YEARS Assigned and expired.	Machinery and Boiler Surveys (including date of N.B., if any).
For Special Survey.		
Date of last Survey and of Periodical Surveys.		
F.E. attached		

Particulars of Examination and Repairs (if any) LMC

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? Yes

Where a thorough examination was not done, state for what reasons? all examined

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Yes

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 180 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam? 180 lbs

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boiler? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? Yes and of the Donkey Boiler? Yes

Has the screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? Yes or is it without liners? Yes

Has the shaft now been changed? No If so, state reasons -

Has the shaft now fitted new? Yes Has it a continuous liner? Yes or two liners? Yes or is it without liners? Yes

What is the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 32

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete Examination made of Cylinders, Pistons and Slide valves. Thrust, crank, and screw shafts examined. Air, feed bilge pumps with condenser, and their connection examined. Circulating Pump and Connecting examined. Sea cocks, and their fastenings examined. Boilers examined internally, and externally, and found Satisfactory.

All defects made good

General Observations, Opinion, and Recommendation:— The machinery of this vessel is in a safe working condition and in my opinion is eligible to have L.M.C. 10.20 entered in the R.B.

Survey Fee (per Section 25) £ 19

Special Damage or Repair Fee (if any) (per Section 25.) £11

Travelling Expenses (if chargeable) £1

Received by me, J.W. Johnstone

Committee's Minute TUE. NOV. 30 1920

Assigned L.M.C. 10.20

J.W. Johnstone
Engineer Surveyor to Lloyd's Register of Shipping.

CERTIFICATE WRITTEN

TUE. JAN. 24 1922
TUE. MAR. 27 1922
Lloyd's Register Foundation
008541-008549-0090

PLEASE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to