

19 JAN 1954

SHIP NAME

"EL BUARO"

REPORT

L.R. 20 FEB 1954

No. 1420

Standing Conditions of Class: NONEAssignment of Class (B) (~~As before~~ or None)Location of Present Survey: (~~Afloat~~ and in dry dock)

Minor repairs.

Recommendation:SUBMITTED record of docking 9,53
be assigned as recommended.

9,53 Callao.

IT IS FURTHER SUBMITTED the Surveyors be advised it is
concluded there is a stream anchor on board.see later blue
chart of 4/5/54

© 2021

Lloyd's Register
FoundationJBM.
11.1.54