

POSTPONED SURVEYS

Case of the S.S. "ESSO BACHAQUERO" No. 09257 in R.B.

Built 1937-6 Tonnage _____ Owners _____

Class _____ Port of Registry _____

Last docking date _____

Surveys due Special Survey due 5.54
Last docking 3.54
Boiler Survey due 4.55
"Laid up surveys overdue" assigned 23.8.55
For conditions of class see endorsement 17.8.55

Proposed to be _____

Remarks From the attached letters it appears that the vessel is now engaged on a service limited to Lake Maracaibo and a portion of the Gulf of Venezuela, the vessel having been removed from tieup last October for repairs etc.

It appears that the Owners have no intention of keeping the ship in the Society's class.

Chief Surveyors' recommendations _____

Committee's Minute _____

Decision _____

FRIDAY - 4 MAY 1956

Non-compliance

Disals

*Patched
Mills*

© 2020

Lloyd's Register
Foundation

008559-008568-0096

GENERAL COMMITTEE

Thursday,

17th May, 1956

Classing Committee's
decision confirmed.

R. A. J.



© 2020

Lloyd's Register
Foundation

