

Lloyd's Register of Shipping. *Jhd 3925*

-7 JUL 1941

Ship's Name "EMPIRE SUCCESS".

Official No. 167430.

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in _____

The freeboards of this vessel have been reassigned at this time.

The openings in the combined bridge & poop front have been permanently closed & suitably stiffened.

All overboard scuppers from the combined bridge & poop spaces have been permanently closed & the spaces drained to the bilges by scupper pipes.

The new freeboard markings have been verified & cut in on sides of the vessel.

Additional accommodation has been fitted at this time at the fore end of the bridge space (p.s.)

3 sidelights & 2 sidelights, all with deadlights of substantial construction have been fitted in shell & bridge front respectively.

W.C. with gate valve fitted. *with secondary means of control.*

Steel companionway fitted on bridge deck 5'-9" x 36" x 6'-6" high with strong hinged wood door 4'-6" with 21" coaming.

3 mushroom vents fitted to accommodation.

W.R. Robinson 6/41

SURVEYOR TO LLOYD'S REGISTER.

A copy of this information has been placed on board the vessel.

W.R.
10/7/41

W.R.

