

RISTA

COPY.

Lloyd's Register of Shipping.

FOR LONDON OFFICE.



Port DUNEDIN N.Z.

July 3rd 1931.

This is to Certify that

William John Crawford

the undersigned Surveyor to this Society did at the request of the Manager of the Union S.S.Co.N.Z.Ltd. issue the following interim certificate for freeboard for

S.S. "KAWATIRI" ex "SHAHRISTAN". O.N.75355.

Official No.136153 and hereby certify -

- (a) That the centre of such disc is placed at four feet one & a half inches below the upper deck line marked under the provisions of the Merchant Shipping Acts.
- (b) That the position of the lines to be used in connection with the disc shall be as follows : -

Maximum load line in fresh water. The upper edge of this line is six inches above the upper edge of the horizontal line passing through the centre of the disc.

Maximum load line in Indian Summer. The upper edge of this line is four & a half inches above the upper of the horizontal line passing through the centre of the disc.

Maximum load line in Summer. The upper edge of this line is on the same level as the upper edge of the horizontal line passing through the centre of the disc.

Maximum load line in Winter. The upper edge of this line is four inches below the upper edge of the horizontal line passing through the centre of the disc.

Top of statutory deck line above the steel deck at side one & three quarter inches.

This Certificate is to remain in force only so long as the vessel remains in her present class, provided that no change has taken place in the structural condition of those deck erections in respect of which deductions have been made for freeboard.

W. J. Crawford
Surveyor to Lloyd's Register.

© 2019

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

008608-008617-0296

DARD recommended amount
Fresh Water Line

above centre of Disc