

DISCLOSED SECTION.

Rpt. 8.

No. 117551

(Received at London Office)

No. 117551

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of...
No. in Survey held at... Date, First Survey... Last Survey... 19...
Reg. Book. 45882 on the Wood, Iron or Steel See See "SEDDON" (No. of Visits...)

TONNAGE: Built at Beverley By whom Coak, Walton & Gemmill Ltd When 1916 MONTH 11
GROSS 296 Owners Braig Stores (Aberdeen) Ltd. Owners' Address...
UNDER DEK 263 Managers Joseph Braig (If not already recorded in Appendix to Register Book).
NET 115 Port belonging to Gruinley

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...
Cell/D/Bor/D/BA... feet; uE & B... feet; f... feet
total capacity... tons. FPT... tons; APT... tons; MT... feet... tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)
CHARACTER: * for Special Survey, Date of last Survey and of Periodical Surveys.
Machinery and Boiler Surveys (including date of N.B., if any).
1100A1 time 2.46
Stm Trawler BS 7.48
7.48 TS 7.48 CC
SS Set 2nd No 3.2.46
haid up Pending Survey.

Last Report, No. 24541. Port Gruinley.
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?
REPAIRS, OR EXAMINATION AS PER RULE, FOR

DESCRIPTION OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
newed ...								
Removed and Falred or Repalred								
Falred or Repalred in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.) When fitted, Month Year
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	Boats
aulking of Decks	Cement or Asphalt	Oil Bunkers	Masts, Yards, &c.
Coamings	Rudder	Scuppers	Condition, how ascertained (State if wedges removed.)
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Equipment letter
Outside Plating	Windlass	Hatches	Anchors, No. of
" " In way of sidelights	Have pumps been examined and found efficient?	Planking	Cables (State if now ranged)
Frames	Have Sluce Valves been examined and found efficient?	Caulking	" length mean diamr. (on board.)
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	" Rule length size
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Chain Locker
Transverses	Alr and Sounding Pipes	Transoms, Pointers & Crutches	Hawsers & Warps
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Standing and Running Rigging
Keelsons		" " at other places	Sails
Stringers		Swingers, Clamps & Shelves	
Inner Bottom Plating		Salting (State if examined.)	
Have the Tanks been examined Internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute FRL 1 JUN 1951
Character Assigned Withdraw class
Write also 2 inser (- - -)
Surveyor to Lloyd's Register of Shipping.
Special GENERAL COMMITTEE
Thursday 14 June 1951.
Classing Committee's decision confirmed.
2021
008618-008627-0039