

"POKUCIE".

This trawler was built at Selby 1917-12 and then classed
 *100A1 "Stm.Trawler".

It was arranged for the class to be omitted 3,51 in
 view of the absence of information regarding Owners' intention
~~about~~ the carrying out of the outstanding surveys and the
 maintenance of the class of the ship.

In anticipation of a request from the Polish Trading
 Mission, the ROTTERDAM Surveyors in a letter dated 29.11.52,
 desired the necessary information to enable them to submit
 the ship for reclassification.

IT IS SUBMITTED they be informed that to have the
 ship's character reinstated in the Register Book as formerly,
 it will be necessary for:-

- 1) The requirements of a Periodical Special Survey (C)
 to be complied with, including a drilling of the
 structure if necessary where signs of wastage are
 evident (ship 35 years old).
- 2) Any major repairs which have been effected to the
 structure since the ship was disclasse~~d~~ to be
 specially examined in order to ascertain the
 character of the workmanship and confirm that the
 materials used are in accordance with the Rules.
- 3) Structural alterations which may have been carried
 out since the ship's class lapsed and which affect
 the longitudinal and/or transverse strength of the
 ship to be reported.
- 4) Full particulars of the equipment on board, including
 weights, tests, etc. of anchors and tests, etc. of
 chain cable to be furnished, for re-instatement of
 the Figure '1', and
- 5) the Special Survey to be held at a port where the
 Society is represented, in view of the age of the
 ship and the importance of the survey,

With reference to the request for plans of Midship
 Section etc. it is FURTHER SUBMITTED the Surveyors be
 informed that the First Entry Report together with the
 plans requested of a Sister ship were forwarded to them
 1.12.52.

*A complete SS of the
 machinery should be
 held, including an examination
 of the screw shaft.*

*For Lloyd's Regt (H)
 L/A*

L/A

8.12.52.

© 2021

Lloyd's Register
 Foundation