

8 DEC 1920

Surveyors 7. 12. 20.

Received from Chief Surveyors

NAME Steel S.S. "TOCANTINS".

Report N.Yk. No.18113.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

2nd No. 1 SURVEY PARTLY HELD. &c.

6.19.

When proposed to be completed

Survey held, &c.,

The 2nd special survey No.1, due 6.19, has been part held.  
Some damage through fire requires to be permanently repaired.

The Rio de Janeiro Surveyor now states that he visited the vessel and arranged with the Owner's representative for the necessary requirements for the survey, who promised to advise the Surveyor when the vessel was ready for inspection, but that the vessel was required to load a cargo for the U.S.A., and has sailed for Santos, no part of the survey having been held.

They add the Owners, however, now state that on her return from the present voyage, arrangements will be made for the survey to be completed.

It is submitted for consideration whether action might be deferred provided the arrangement be adhered to.



© 2021

Lloyd's Register Foundation

7. 12. 20.

008641-008647-0070