

should be summarised in the form below. When, at a Special
Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain
Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq)
which is to be attached to this Report.

Dkg 0.50

(To be attached to Genoa Report No. 22350)

Port of Genoa

15th May, 1957

REPORT ON MASTS, SPARS, AND RIGGING.

Sirs,

Having, in accordance with your instructions,

examined the Masts, Spars, Iron Work of same, and Rigging, of the
of Vessel s/s "IOANNIS INGLESSIS", 7035 Tons Gross of Piraeus

on (Date of examination) 11th April, 1957

to report that I found everything in good order

Mario Fassu

Surveyors,
Lloyd's Register of Shipping,
Genoa



© 2021

Lloyd's Register
Foundation

008648-008655-0035

now veri
no
VEY.
flan
ets o
ed &
rep
ave
nt
no
plan
unke
th
CO
ams
sent to
ook co
emain
t r
su
the
ate
J.
Surve