

George Brown & Co. (Marine) Ltd., Greenock.

Yard No. 236

Similar to the "EMPIRE FRIEDA"

t to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME S.S. "EMPIRE LOLA" REPORT Grk No. 23305For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey FIRST ENTRY ~~When due~~.....

LOCAL "For towing services" "Fitted for oil fuel 4,46, FP above 150°F"

"Butts of shell plating pt. elec. welded"

DTf 6' 12t, FPT 6t, APT 27t

BK 7", 3BH, pt. Asp., pt. Cem., Lloyd's A & CP

O.L. 123.3'

Extreme breadth over belting 29.4'



20.5.46

Lloyd's Register
Foundation

008669-008678-0274