

Lloyd's Register of Shipping,

40.00

(MEIKAI BUILDING)

1.00

32, AKASHI-MACHI,

KOBE, 12th. April 1930.

Cert. No. 2467.

This is to Certify that at the request of Messrs. The Kobe Steel Works Ltd., Kobe,

the Open Hearth Steel Forgings or ~~Castings~~ named below ^{was}~~were~~ examined and tested at their works on 31st. March and 4th. April 1930.

and found to be as far as could be ascertained, sound and free from defect.

One P.S. Intermediate shaft 15½" black dis.

Examined in black forged condition.

~~Drop tests~~

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x ½" x 180°
D 3639A1	30.3	35	Good.

This shaft is intended for Yokohama Dockyard

Ship No. 179 or 180

and ~~was~~ have been stamped as follows:-

Fee Yen 40.00


Expenses „ 1.00

D3639A1
LLOYD'S
No. 2467
4-4-30
A.D.M. L.R.

A. D. Morris

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
“While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society.”



W.H.

Lloyd's Register of Shipping

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 18th April 1930.

Cert. No. 18467

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe,

the Open Hearth Steel Forgings or Castings named below were examined and tested at their works on 1st March and 4th April 1930.

and found to be as far as could be ascertained, sound and free from defect.

One 15" diameter shaft 15' long, black die.

Test Mark	Tensile in Tons	Elongation in 2"	Bend 1" x 1/2" x 180°
D 36321	30.8	58	Good

This shaft is intended for Yokohama Dockyard and has been stamped as follows:—

Expenses 1.00
Yen 40.00
No. 18467
4-4-30
A.D.M. L.R.

Surveyor to Lloyd's Register

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy of report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."



Lloyd's Register Foundation