

COPY

Lloyd's Register of Shipping.

MEIKAI BUILDING

32, AKASHI-MACHI,

KOBE.

6th September 1932.

CERT. No. F. 1456.

THIS IS TO CERTIFY that at the request of

Messrs. Kawasaki Dockyard Co. Ltd., Fukui Plate & Sheet Mills, Kobe,

the open hearth mild steel Boiler quality Plates made to the order of Messrs. Mitsubishi Zosen Kaisha, Ltd., Nagasaki,

and intended for Repairs, 522 were inspected and tested at their works on dates as stated below.

Samples taken from this material were subjected to the tensile, and bend tests prescribed by the Rules of this Society for Boiler material with satisfactory results.

For identification of material see signed invoice attached hereto.

No. 6097.

RESULTS OF TESTS

of Test	Item No.	Test No.	Charge Mark.	Thickness.	Breadth	Area	Total Tons.	Tons per square inch	Extension in 8 ins. %	Bend.
932.										
			<u>Plating Quality:-</u>							
3/8	1	B1078B	III-2513	.52 13	1.99	1.035	29.156	28.17	26.0	Good
1/8	3	A9177BI	-4714	.68 17	1.97	1.340	35.554	26.53	30.0	"
"	4	A9175B	I-4711	.76 19	1.50	1.140	30.875	27.08	27.0	"
"	7	A9175B	I-4714	.55 14	1.97	1.084	29.103	26.85	26.5	"
"	8	A9176B	I-4711	.68 17	1.97	1.340	37.013	27.62	24.0	"
4/8	9	B1821B	I-4796	.51 13	1.98	1.010	28.585	28.30	27.0	"
			<u>Shell Quality:-</u>							
4/8	2	B1822B	I-4796	.42 10	1.98	.832	25.638	30.81	24.0	"
3/8	5	B10790	III-2513	.51 13	1.98	1.010	28.603	28.32	26.0	"
4/8	6	B1823A	I-4796	.40 10	1.96	.784	24.469	31.21	22.5	"
1/8	11	A9172B	I-4712	1.00 25	1.22	1.220	34.306	28.12	25.0	"
3/8	12	B816B	III-2513	.80 20	1.50	1.220	33.507	28.06	28.0	"
				.80 20	1.50	1.220	33.942	28.29	26.0	"
			- THE END -		13	Pieces.	2.761	Kgs.		

Fee Yen

Expenses "

Mordant W. Parker

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."

