

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

13th January, 1922.

Dear Sir,

H. I have to acquaint you that on the occasion of the steamer "MANOA" being under survey at Cardiff in March/May last, the Society's Surveyors at that port reported that the main boiler furnaces - which were all found to be more or less distorted - had been set up and they recommended that these furnaces should be examined before the end of December, 1921.

The Society's Surveyor at Montreal now writes that he is informed by the Owners that the vessel is proceeding from Halifax to Liverpool and London and that after discharging she will proceed to your port where repairs to the boilers will be carried out.

In the circumstances I have to request that you will give the case the necessary attention, and for your information I think it well to add that the vessel retains her class subject to the tank top plating being examined and ceiling fitted in way of the hatchways if found necessary, and to the shell plating repaired by electric welding being specially examined at the next dry-docking.

I am, Dear Sir,
Yours faithfully,

G.H.C.Bahr, Esq.,

BREMEN:

Secretary.

008641-008694-6231

© 2021
Lloyd's Register
Foundation