

Screw shaft examined.

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

S. 3. 26-

L.S.
14/3/25.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation