

Icebreaker

18 DI

nt to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel Tw. Sc. "N.B. McLEAN"

Report

Lon

No.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ature of Survey

When due

The Screwshaft Survey became due in 8,33.

In reply to enquiry the Montreal Surveyor forwards a letter from the Owners intimating that they do not propose to have the vessel retained in class.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu indicating withdrawal of class at the Owners' request.

Withdraw class

Insert ...



© 2020

Lloyd's Register  
Foundation

008720-008727-0159

14.12.33