

to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

23 NOV 1928

Vessel's NAME Steel Tr. Sc. "M. S. C. BOLLIN". Report Lon. No. 93262a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/192.)

Date of Survey \_\_\_\_\_ When due \_\_\_\_\_


The S.S. No.1 became due 10,28.

The Owners now state that it has been decided not to maintain the classification.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...





© 2020

Lloyd's Register  
Foundation

22.11.28.

008728-008733-0177