

s/s "M. S. C. Bollin."

Grk 18303.

It is submitted the Greenock Surveyors be informed it is concluded that a spare set of bilge pump valves has been placed on board, but as this is not reported they should state if this is so.



© 2020

J.W.D. 16/10/74

Lloyd's Register Foundation

008728-008733-0188