

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor..... **30 OCT 1958**

4E

SHIP'S NAME..... HONGKONG MARU..... REPORT..... Kob..... No..... 6113

C.S. Advanced. Docking.

DBS (Scotch) due 5.59, now held.
DBS (Vertical) due 12.60, now held.

The ballast pump water end found somewhat corroded and the Surveyor recommends this item be re-examined before the end of 9.59, considered efficient meantime.

Some repairs carried out to Scotch Boilers.

IT IS SUBMITTED that this vessel is eligible for the RECORD, DBS 9.58, subject as recommended.

CDM
30.10.58.



© 2020

Lloyd's Register
Foundation

008734-008742-0029