

Has Shaft now fitted been previously used?

Has Shaft now examined/fitted a continuous liner?

4E

26 JUN 1958

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....


SHIP'S NAME..... "HONGKONG MARU"..... REPORT..... Yka..... No..... 2600

DBS (SB) due 9.58, now held.

Docking.

IT IS SUBMITTED that this vessel is eligible for THE RECORD, DBS (SB) 5.58.

Note - Vertical donkey boiler not due for Survey.



© 2020

Lloyd's Register  
Foundation

20.6.58.