

15 SEP 1959

Received from Chief Ship Surveyor.....

SHIP'S NAME "GENERAL LAS HERAS"

REPORT

B.As.

No. 30581

standing Conditions of Class: SUBJECT to pitting in rudder and sternframe and shell plates in 'E', 'F' & 'G' strakes (p & s) being specially examined by next drydocking, and to anchor joining shackles (p & s) being tested to Rule requirements as soon as possible.

S.L. Appendix. (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (B) due 10,59.

Location of Present Survey: (~~Afloat~~ and in dry dock)

Special Survey: Wear and tear repairs including part subject item.

Special Features:

Interim Certificate in order (Yes-~~No~~-None)~~x~~

Items Outstanding: (If any for S.S.)

NONE.

Work completed by ~~xxx~~

Recommendation:

SUBMITTED record of 'DS 6,59' and Notation of 'SS 6,59' be assigned as recommended, subject to anchor joining shackles (p & s) being tested to Rule requirements at the earliest opportunity, and to rudder and sternframe (pitted) being specially examined next drydocking, but without other condition.

DS 6,59 Subject without

IN S.R.L. APPENDIX.

Shell plates E.8 & F.7 (p.s.) indented.

OFFICE NOTE

Structural arrangements in order - 23.3.55.

See entry dated 1/10/59

Amended 3/9/59



© 2000

Lloyd's Register Foundation

008751-008752-0092-1