

"BRACONGLEN"

Before this case receives the consideration of the Committee, it is submitted the Surveyors be advised it is noted that 60 fathoms of chain cable were found wasted of a mean diameter of  $5/8$ ", but they should be requested to forward details of mean diameter of remaining 60 fathoms of chain cable as this is not clear from the report.

*See endorsement  
d. 23/11/61*

*P. J. - C  
9/11/61*



© 2021

Lloyd's Register  
Foundation

008753 - 008758 - 0086