

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
                          Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

16th April, 1963

C  
DNS/RW

Dear Sirs,

M.V. "HELGA SMITH"

As a result of a survey carried out by the Gothenburg Surveyors on the 20th March last, the Committee have continued the vessel's class subject to fractures in sheerstrake, deck in way of deckhouse front (port and starboard), in sheerstrake in way of freeing ports forward of midship deckhouse and in sheerstrake in way of aft end of recess for gangway (starboard side) being specially examined and dealt with as necessary by the end of next month.


I shall be glad if you will inform the Owners accordingly, and ascertain and let me know what arrangements they propose to make for the above items to be dealt with.

The vessel's class has also been continued subject to the propeller being specially examined and dealt with at the next drydocking, before the end of May, 1963, and the Owners' intentions regarding this matter will also be appreciated.

Yours faithfully,

pro Clerk to the  
Classification Committee

Stockholm Surveyors,



© 2021

Lloyd's Register  
Foundation

00 8753 - 00 8758 - 0195