


COPY

008753 - 008758 - 0207

Ship's name *HELGA SMITH*Port *SKIN*
*CIN*No. *14076*
*20127*Class is subject to — *NIL*Last survey date *29/1/63*
8/2/63

Docking *Wia down 2.5"/ft.*
DBS due 9/62/ now held. Grooves not cut in
accordance with Instructions Part 3b 1957, item 1.15.5.5.1
After subsequent examination of the abas with the ship
afloat the C/M Surveyors report examination of the propeller
on account of alleged contact with ice, three blades
found slightly bent on trailing edges as to
recommend the propeller to specially examined and
deal with at the next dry docking before end 5/63.

**It is submitted that this
 vessel is eligible for THE
 RECORD.** *DBS 1/63*

*Subject as recommended**By*
3/1/63

© 2021

Lloyd's Register
Foundation**S.R.L. - Appendix Note***To 5511 Section 7E*
End. E.2*Instructions, Part 3b 1957, item 1.15.5.5.1*
*conflict with no daisy border**Noted SRL REN*