

"HELGA SMITH" - Skm. Rpt.No.13657.

Before this case receives the consideration of the Committee IT IS SUBMITTED the Surveyors be requested to furnish the mean worn diameter of Nos.1,2 & 3 lengths of chain cable on the port side which were found worn below renewal diameter.

*See letter
re
21/6/62.*

*W.O.T.
12/6/62.*

270
45



© 2021

Lloyd's Register
Foundation

008753 - 008758 - 0215